



Storage conditions of Felt

- dry, roofed rooms
- ventilated rooms, natural ventilation at best
storing 20 cm above floor level for best air flow
- avoid direct sunshine and humidity
- moth protection using ant moth preparations
- pollution protection, boards – cover with plastic wrap,
Other felt products – in plastic bags

Last update : 01.11.2019

Created : 11.02.2014

Jana Vážná

Quality control